OPERATOR QUALIFICATION FIELD INSPECTION PROTOCOL FORM

Inspection Date(s):	January 6, 2014
Name of Operator:	White County Housing Authority
Operator ID (OPID):	39072
Inspection Location(s):	Norris City, Crossville and Grayville, Illinois
Supervisor(s) Contacted:	Mike Wendling
# Qualified Employees Observed:	0
# Qualified Contractors Observed:	1

Individual Observed	Title/Organization	Phone Number	Email Address
Mike Wendling	Utility Safety and Design Inc.	618-392-5502	mwendling@usdi.us

To add rows, press TAB with cursor in last cell.

PHMSA/State Representative	Region/State	Email Address
James Watts	Illinois	jwatts@icc.illinois.gov

To add rows, press TAB with cursor in last cell.

Remarks:

A table for recording specific tasks performed and the individuals who performed the tasks is on the last page of this form. This form is to be uploaded on to the OQBD for the appropriate operator, then imported into the file.

9.01 Covered Task Performance

Verify the qualified individuals performed the observed covered tasks in accordance with the operator's procedures or operator approved contractor procedures.

9.01 Inspection Results (type an X in exactly one cell below)		Inspection Notes
X	No Issue Identified	
	Potential Issue Identified (explain)	
	N/A (explain)	
	Not Inspected	

9.02 Qualification Status

Verify the individuals performing the observed covered tasks are currently qualified to perform the covered tasks.

	nspection Results a X in exactly one cell below)	Inspection Notes
X	No Issue Identified	
	Potential Issue Identified (explain)	
	N/A (explain)	
	Not Inspected	

9.03 Abnormal Operating Condition Recognition and Reaction

Verify the individuals performing covered tasks are cognizant of the AOCs that are applicable to the tasks observed.

9.03 Inspection Results (type an X in exactly one cell below)		Inspection Notes
X	No Issue Identified	
	Potential Issue Identified (explain)	
	N/A (explain)	
	Not Inspected	

9.04 Verification of Qualification

Verify the qualification records are current, and ensure the personal identification of all individuals performing covered tasks are checked, prior to task performance.

	nspection Results X in exactly one cell below)	Inspection Notes
X	No Issue Identified	Last Qualification was completed in January 2014.
	Potential Issue Identified (explain)	
	N/A (explain)	
	Not Inspected	

9.05 Program Inspection Deficiencies

Have potential issues identified by the headquarters inspection process been corrected at the operational level?

9.05 Inspection Results (type an X in exactly one cell below)		Inspection Notes
	No Issue Identified	
	Potential Issue Identified (explain)	
X	N/A (explain)	
	Not Inspected	

Field Inspection Notes

The following table is provided for recording the covered tasks observed and the individuals performing those tasks.

		Nam			
		Mike Wendling			
No	Task Name	Correct Performance (Y/N)	Correct Performance (Y/N)	Correct Performance (Y/N)	Comments
1	Locating	Y			
2	Short Locating	Y			
3	AOC's	Y			
4					
5					
6					
7					
8					

Operations and Maintenance Records Review

If performing an operations and maintenance records review in the course of your inspection, please review a sample of the qualifications of the individuals performing those O&M tasks that are covered under Operator Qualification and check the records for compliance to 192.807 or 195.507.

192.807 or 195.507	Records supporting an individual's current qualifications shall be maintained while the individual is performing the covered task. Records of prior qualification and records of individuals no longer performing covered tasks shall be retained for a period of five years.	Sat.		Not Checked
	Comments: Review of USDI records indicate Mr. Wendling was currently qualified for the tasks observed. His last qualifications v 2014.	vere coi	npleted in	January